rison Report

			Priority Issues Data				0-5 Year Cumulat			
		Percent of		Percent of				Percent of		
V		Total CRV	DMB	Total DMB	FCI	Rating	DMB	Total DMB	FCI	Rating
3,040			$970,864		1.48%	GOOD	$3,593,585		5.02%	FAIR
	GOOD									
83	FAIR									
15	GOOD									
1.	POOR									
0.										
										GOOD
1,300		16.0%	$34,354	3.5%	0.30%	GOOD	$480,955	13.4%	4.20%	GOOD
5,235		0.7%	$5,925	0.6%	1.15%	GOOD	$33,233	0.9%	6.45%	FAIR
9,465		10.7%	$115,342	11.9%	1.50%	GOOD	$480,592	13.4%	6.25%	FAIR
5,610		6.1%	$167,691	17.3%	3.85%	GOOD	$429,028	11.9%	9.85%	FAIR
2,785		4.7%	$93,027	9.6%	2.75%	GOOD	$228,338	6.4%	6.75%	FAIR
2,660		12.1%	$104,192	10.7%	1.20%	GOOD	$547,008	15.2%	6.30%	FAIR
1,360		0.2%	$0	0.0%	0.00%	GOOD	$12,852	0.4%	7.50%	FAIR
7,895		3.5%	$6,195	0.6%	0.25%	GOOD	$167,258	4.7%	6.75%	FAIR
2,195		12.2%	$0	0.0%	0.00%	GOOD	$240,410	6.7%	2.75%	GOOD
1,500		0.6%	$0	0.0%	0.00%	GOOD	$0	0.0%	0.00%	GOOD

Campus: Main
Bldg. No: 01
Building: Activities
Area: 36,190sf Yr Built: 1975 Floors: 1

Use Types:
35 % Athletic
35 % Student Union
30 % Natatorium

Notes: original building - 35,194 SF
2007 - Bookstore renovation/addition (+1,000 SF)

System	%	$	Immediate	1-5 Years	6-10 Years	11+ Years	System/Component Notes
HVAC	24	$2,633,954	10	5	10	75	

Campus: Main
Bldg. No: 01
Building: Activities
Area: 36,190sf Yr Built: 1975 Floors: 1

Use Types:
35 % Athletic
35 % Student Union
30 % Natatorium

Notes: original building - 35,194 SF
2007 - Bookstore renovation/addition (+1,000 SF)

System	%	$	Immediate	1-5 Years	6-10 Years	11+ Years	System/Component Notes
Primary/Secondary	10	$1,097,481	0	0	20	80	Primary - good condition
			$0	*$0*	*$219,496*	*$877,985*	Secondary - good condition

2007 assessment:
No reported problems

2009 Assessment:No changes reported.

2010 assessment:
Campus primary service upgraded by Consumers Energy to provide additional capacity.

2011 - 2015 Assessment: No changes reported.

2016 Assessment: No changes reported. No reported problems.

2018 Assessment: Building served by 480/277V, 3-phase service with 600A capacity. Main gear and most distribution gear is Federal Pacific QMQB Style with fusible switches for overcurrent protection. This equipment is no longer available, but still maintainable. Need to clean and tighten all connections.
Emergency panel tapped ahead of the main switch is no longer code-compliant.

2019 Assessment: Federal eMe.6 (an)-0.6 (d ,3-8.9 (r)-1.3 4l)-1.3 (i)-m 4o (i)-1.3 (c)-8.9 (e)-0.6 (w)38.5 (

Campus: Main
Bldg. No: 01
Building: Activities
Area: 36,190sf Yr Built: 1975 Floors: 1

Use Types:
35 % Athletic
35 % Student Union
30 % Natatorium

Notes: original building - 35,194 SF
2007 - Bookstore renovation/addition (+1,000 SF)

System	%	$	Immediate	1-5 Years	6-10 Years	11+ Years	System/Component Notes
Doors	2	$219,496	0	5	10	85	Exterior:
			$0	*$10,975*	*$21,950*	*$186,572*	Original hollow metal and alum frame full lite doors

2001-some exterior doors to gym require replacement

2003-worn/damaged exterior doors replaced

Interior:
Original interior doors, mostly solid core wood.
2005-Wood doors due for refinishing

2007 assessment:
several interior doors replaced. Approximately 14 original doors remaining, due for refinishing.

2009 Assessment: 2008-gym storage room doors replaced

2010, 2011, 2012 Assessment:No changes reported.

2013 assessment:
Elevator equipment room door relocated from pool to corridor to reduce corrosion damT220 >>Be

Campus: Main
Bldg. No: 02
Building: Barn Theater
Area: 3,932sf Yr Built: 1917 Floors: 2

Use Types:
100% Auditorium

Notes:
2016-Building infrequently used.
2007-seating replaced, sprinkler system added, egress improved.
2016-the exterior envelope was replaced with new barn siding.
This building cannot be replaced with an equivalent building.

System	CRV of System %	CRV of System $	Pct. of system value to budget for repair/replacement: Immediate	1-5 Years	6-10 Years	11+ Years	System/Component Notes
Structure	15	$142,994	0 *$0*	0 *$0*	20 *$28,599*	80 *$114,395*	Wood structure exposed on interior, no reported problems. 2003-Chimney repaired. 2007 assessment: No changes, no reported problems. 2009-2015 Assessment: No changes reported. 2016 Assessment: No changes reported. No reported problems. 2018 Assessment: Modifications may trigger structural upgrades of building. This building would be difficult to bring up to current structural requirements in building code. Structure comprises of wood timbers and gambrel barn roof form. 2019 Assessment: No changes reported. No reported problems. 2021 Assessment: No changes reported. No reported problems.
Roof	7	$66,731	15 *$10,010*	10 *$6,673*	25 *$16,683*	50 *$33,365*	Tin roof/ some asphalt shingle on later addition 2007 assessment: No changes, no reported problems. 2009-2012 Assessment: No changes reported. 2013 Assessment: Metal barn roof due for repaint. Asphalt shingles in fair condition. 2014-2015 Assessment: No changes reported. 2018 Assessment: Existing tin roof on original barn, with asphalt shingles on addition. No changes reported. No reported problems. 2019 Assessment: No changes reported. No reported problems. 2021 Assessment: No changes reported. No reported problems.

Campus: Main
Bldg. No: 02
Building: Barn Theater
Area: 3,932sf Yr Built: 1917 Floors: 2

Use Types:
100% Auditorium

Notes:
2016-Building infrequently used.
2007-seating replaced, sprinkler system added, egress improved.
2016-the exterior envelope was replaced with new barn siding.
This building cannot be replaced with an equivalent building.

System	%	$	Immediate	1-5 Years	6-10 Years	11+ Years	System/Component Notes
HVAC	20	$190,659	25	20	0	55	System upgraded in 1991
			$47,665	*$38,132*	*$0*	*$104,862*	Fan unit above stage noisy, often shut off during performances. Temperature varies significantly from low seats to high seats.

2007 assessment: No changes, no reported problems.

2009 Assessment: No changes reported.

2011 assessment: No changes reported.

2012 assessment: Barn not on campus-wide building automation system.

2013 assessment:
Barn ground mounted twin-condensor A/C unit installed in 1991 is near end of expected life. Budgeting for replacement recommended.

2014 Assessment: No changes reported.

2015 Assessment: No changes reported. HVAC system remains near end of expected life.

2016 Assessment: No changes reported.

2018 Assessment: The barn Theater HVAC is served by gas-fired heat and DX cooling AHUs/RTUs and both in good condition, should continue to function.

Campus: Main

Use Types:

Notes:

Campus: Main

Us: Main

Campus: Main
Bldg. No: 02
Building: Barn Theater
Area: 3,932sf Yr Built: 1917 Floors: 2

Use Types:
100% Auditorium

Notes: 2016-Building infrequently used.
2007-seating replaced, sprinkler system added, egress improved.
2016-the exterior envelope was replaced with new barn siding.

Campus: Main
Bldg. No: 02
Building: Barn Theater
Area: 3,932sf

Use Types:
100% Auditorium

Notes: 2016-Building infrequently used.
2007-seating replaced, sprinkler system added, egress improved.
2016-the exterior envelope was replaced with new barn siding.

Campus: Main
Bldg. No: 03
Building: Cold Storage
Area: 3,880sf Yr Built: 1967 Floors: 1

Use Types:
100% Storage

Notes: Pre-engineered building

System	%	$	Immediate	1-5 Years	6-10 Years	11+ Years	System/Component Notes
Structure	35	$59,976	0	0	0	100	No reported problems
			$0	$0	$0	[illegible]	

2021 Assessment: No changes reported. No reported problems.

Campus: Main
Bldg. No: 03
Building: Cold Storage
Area: 3,880sf Yr Built: 1967 Floors: 1

Use Types:
100% Storage

Notes: Pre-engineered building

System	CRV of Syste %	CRV of Syste $	Pct. of system value to budget for repair/repla Immediate	1-5 Years	6-10 Years	11+ Years	System/Component Notes
Cladding	20	$34,272	0	10	10	80	Metal siding, minor damage, not an issue
			$0	*$3,427*	*$3,427*	*$27,418*	
							2007 assessment:No changes
							2009-2015 Assessment: No changes reported.
							2016, 2018, 2019, 2021 Assessment: No changes reported. No reported problems.
HVAC	0	$0	0	0	0	100	N/A
			$0	*$0*	*$0*	*$0*	
							2014 - 2015 Assessment: No changes reported.
							2016, 2018, 2019, 2021 Assessment: No changes reported. No reported problems.
Plumbing/Drainage	0	$0	0	0	0	100	N/A
			$0	*$0*	*$0*	*$0*	
							2014 - 2015 Assessment: No changes reported.
							2016, 2018, 2019, 2021 Assessment: No changes reported. No reported problems.

Campus: Main

Use Types:

Notes:

Campus: Main
Bldg. No: 03
Building: Cold Storage
Area: 3,880sf Yr Built: 1967 Floors: 1

Use Types:
100% Storage

Notes: Pre-engineered building

System	CRV of Syste %	CRV of Syste $	Pct. of system value to budget for repair/repla Immediate	1-5 Years	6-10 Years	11+ Years	System/Component Notes
Doors	10	$17,136	0	10	10	80	Sliding doors, No reported problems
			$0	*$1,714*	*$1,714*	*$13,709*	2007 assessment:No changes 2009-2015 Assessment: No changes reported. 2016, 2018, 2019, 2021 Assessment: No changes reported. No reported problems.
Floors	4	$68,544	0	0	0	100	concrete, No reported problems
			$0	*$0*	*$0*	*$68,544*	2007 assessment:No changes 2009-2015 Assessment: No changes reported. 2016 Assessment: No changes reported. No reported problems. 2018 Assessment: No changes reported. No reported problems. Concrete slab-on-grade. 2021 Assessment: No changes reported. No reported problems.
Bldg., Fire, ADA, Elevators	2	$3,427	0	0	0	100	No reported problems
			$0	*$0*	*$0*	*$3,427*	2007 assessment:No changes 2009-2015 Assessment: No changes reported. 2016, 2018, 2019, 2021 Assessment: No changes reported. No reported problems.

Campus: Main
Bldg. No: 04
Building: Doser Building
Area: 38,013sf Yr Built: 1999 Floors: 1

Use Types:
10 % Administration
45 % Technology Lab
45 % Classroom

Notes:

System	%	$	Immediate	1-5 Years	6-10 Years	11+ Years	System/Component Notes
Structure	15	$1,717,695	0	0	5	95	Foundation wall cracked in 4 locations in computer lab. Some moisture infiltration.
			$0	*$0*	*$85,885*	*$1,631,810*	

2007 assessment:
computer lab exterior wall cracking sealed, no moisture problem noted.

2009 -2012 assessment: No changes reported

2013 assessment:
Small amount of water infiltration in computer lab wall continuing.

2014 Assessment: No changes reported.

2021 Assessment: No changes reported. No reported problems.

Campus: Main
Bldg. No: 04
Building: Doser Building
Area: 38,013sf Yr Built: 1999 Floors: 1

Use Types:
10 % Administration
45 % Technology Lab
45 % Classroom

Notes:

System	CRV of System %	CRV of System $	Pct. of system value to budget for repair/repla Immediate	1-5 Years	6-10 Years	11+ Years	System/Component Notes
Lighting	5	$572,565	0 *$0*	0 *$0*	10 *$57,257*	90 *$515,309*	Insects in fixtures cannot be removed without disassembling fixture, no economical resolution found. 2007 - 2011 assessment:No changes. No reported problems. 2012 assessment: Lighting system upgraded as part of ECM contract. 2013- 2015 Assessment: No changes reported. No reported problems. 2016 Assessment: No changes reported. No reported problems. 2018 Assessment: The main electrical room lacks emergency lighting. Recommend adding this for worker safety. Lighting throughout is T8 fluorescent technology. Classrooms typically have a mixture of switched and dimmed fluorescent indirect linear fixtures. Future remodels should have planned budget to replace with LED lighting for energy savings, maintenance savings, and ease of control/dimming. 2019 Assessment: Replaced 70 light fixtures. No reported problems. 2021 Assessment: No changes reported. No reported problems.
Voice/Data	5	$572,565	0 *$0*	0 *$0*	0 *$0*	100 *$572,565*	No reported problems 2007 assessment:No changes. No reported problems. 2009-2015 Assessment: No changes reported. No reported problems. 2016, 2018, 2019, 2021 Assessment: No changes reported. No reported problems.
Ceilings	3	$343,539	0 *$0*	0 *$0*	5 *$17,177*	95 *$326,362*	No reported problems 2007 assessment: No changes. No reported problems. 2009-2015 Assessment: No changes reported. No reported problems. 2016 Assessment: No changes reported. No reported problems. 2018 Assessment: No changes reported. No reported problems. 2019 Assessment: No changes reported. No reported problems.

2021 Assessment: No changes reported. No reported problems.

Campus: Main
Bldg. No: 04
Building: Doser Building
Area: 38,013sf Yr Built: 1999 Floors: 1

Use Types:
10 % Administration
45 % Technology Lab
45 % Classroom

Notes:

System	%	$	Immediate	1-5 Years	6-10 Years	11+ Years	System/Component Notes
Walls/Casework	2	$229,026	0	0	5	95	Recently repainted 303 & 305
			$0	*$0*	*$11,451*	*$217,575*	
							2007 - 2010 Assessment:No changes reported. 2011 assessment: Routine wall painting performed in corridors. No reported problems. 2012 assessment: No changes reported 2013 assessment: Routine wall painting performed in corridors. No reported problems. 2014 - 2015 Assessment: No changes reported. No reported problems. 2016, 2018, 2019, 2021 Assessment: No changes reported. No reported problems.
Doors	3	$343,539	0	0	5	95	No reported problems

Campus: Main
Bldg. No: 04
Building: Doser Building
Area: 38,013sf Yr Built: 1999 Floors: 1

Use Types:
10 % Administration
45 % Technology Lab
45 % Classroom

Notes:

System	CRV of System %	CRV of System $	Pct. of system value to budget for repair/repla Immediate	1-5 Years	6-10 Years	11+ Years	System/Component Notes
Floors	3	$343,539	0	0	10	90	2005-loose VCT in catering kitchen repaired
			$0	*$0*	*$34,354*	*$309,185*	
							2007 assessment:No changes. No reported problems.
							2009-2015 Assessment: No changes reported. No reported problems.
							2016, 2018, 2019, 2021 Assessment: No changes reported. No reported problems.
Bldg., Fire, ADA, Elevators	2	$229,026	0	0	10	90	fully sprinkled
			$0	*$0*	*$22,903*	*$206,123*	Interior railings warping and failing-do not meet code for weight support, require replacement
							2003-interior railings replaced with painted steel, problem resolved
							2007 assessment:No changes. No reported problems.
							2009-2015 Assessment: No changes reported. No reported problems.
							2016, 2018, 2019, 2021 Assessment: No changes reported. No reported problems.

Campus: Main
Bldg. No: 05
Building: Farmhouse
Area: 2,550sf Yr Built: 1916 Floors: 2

Use Types:
100% Residence

Notes: 2015 - Farmhouse no longer used by College, leased out.

System	%	$	Immediate	1-5 Years	6-10 Years	11+ Years	System/Component Notes
Structure	15	$77,285	0 *$0*	0 *$0*	10 *$7,729*	90 *$69,557*	Wood frame structure on stone foundation. 2007 - 2012 assessment:No changes reported. 2013 assessment: Stone foundation cracking at mortar joints observed. 2014 Assessment: No changes reported. 2015 assessment: Entry porch rebuilt. No changes to building foundation wall. 2016 Assessment: No changes reported. 2018 Assessment: No changes reported. No reported problems. Fieldstone and concrete block foundation. Wood frame house. 2019, 2021 Assessment: No changes reported. No reported problems.
Roof	8	$41,219	5 *$2,061*	15 *$6,183*	20 *$8,244*	60 *$24,731*	Tin roof on original house membrane roof on addition

(obl)4.6 (em)-15[illegible]9.7 (.)]TJ EMC /P <</MCID 196 >>BDC 0 -1.369 TD [(F)-6.4 (i)4.6 (el)4.6 (ds)-9.7

Campus: Main
Bldg. No: 05
Building: Farmhouse
Area: 2,550sf Yr Built: 1916 Floors: 2

Use Types:
100% Residence

Notes: 2015 - Farmhouse no longer used by College, leased out.

System	%	$	Immediate	1-5 Years	6-10 Years	11+ Years	System/Component Notes
HVAC	10	$51,524	0	0	10	90	Newer residential grade system- 1995
			$0	*$0*	*$5,152*	*$46,371*	
							2007 assessment:No changes. No reported problems.
							2009 Assessment:No changes reported.
							2010 Assessment:2010 As9essm14ent:No changes. Ns

Campus: Main
Bldg. No: 05
Building: Farmhouse
Area: 2,550sf Yr Built: 1916 Floors: 2

Use Types:
100% Residence

Notes: 2015 - Farmhouse no longer used by College, leased out.

System	%	$	Immediate	1-5 Years	6-10 Years	11+ Years

Campus: Main
Bldg. No: 05
Building: Farmhouse
Area: 2,550sf Yr Built: 1916 Floors: 2

Use Types:
100% Residence

Notes: 2015 - Farmhouse no longer used by College, leased out.

System	%	$	Immediate	1-5 Years	6-10 Years	11+ Years	System/Component Notes
Ceilings	3	$15,457	0 *$0*	10 *$1,546*	10 *$1,546*	80 *$12,366*	Recently renovated 2007 assessment: 2009, 2011 Assessment: No changes reported. No reported problems. 2016 Assessment: No changes reported. No reported problems. 2018 Assessment: No changes reported. No reported problems. Plaster on lath. 2019, 2021 Assessment: No changes reported. No reported problems.

n e C l t n e c 2009, 2011 Assessment: No changes reported. No reported problems./MCID 128 >>BDC -0.264 (C)-3.1 (

1 2 0 2 , 9 1 2016 Assessment: No changes reported. No reported problems.

Walls/CaseworkiTw 7.8 -0 0.t9 rasewt1200 Tc 0.002 Tw 2.862 0 Td [($15,)-1 (457)]TJ EMC /P 204MCID 132 >>BDC 0 Tc 0 Tw 8.954 0 Td (0)Tj EMC /P <</MCID 13208>BDC -0.002 Tc 0.002 Tw 5.708 0 Td (10)2

Campus: Main
Bldg. No: 05
Building: Farmhouse
Area: 2,550sf Yr Built: 1916 Floors: 2

Use Types:
100% Residence

Notes: 2015 - Farmhouse no longer used by College, leased out.

System	%	$	Immediate	1-5 Years	6-10 Years	11+ Years	System/Component Notes
Floors	5	$25,762	0	20	10	70	Recently renovated
			$0	*$5,152*	*$2,576*	*$18,033*	

Campus: Main
Bldg. No: 05
Building: Farmhouse
Area: 2,550sf Yr Built: 1916 Floors: 2

Use Types:
100% Residence

Notes: 2015 - Farmhouse no longer used by College, leased out.

System	%	$	Immediate	1-5 Years	6-10 Years	11+ Years	System/Component Notes
CRV Totals:	100	$515,235	*$5,925*	*$27,307*	*$61,828*	*$420,174*	$515,235

						0-5 Year Cumulative Data				
$5,925	$0	1.2%	GOOD		$33,233	$23,962	6.5%	$10,300	FAIR	
DMB	EXCESS	FCI	RATING		DMB	EXCESS	FCI	$/YR MAINTAIN	RATING	

Campus: Main
Bldg. No: 06
Building: Kenneth J. Smith Instructional Building
Area: 25,132sf Yr Built: 1966 Floors: 2

Use Types:
40 % Lab
60 % Classroom

Notes: 2015-Formerly called Instruction East
2007-Renovated as part of Ash Building project
2005-Building scheduled for major renovation as part of planned addition in 2006-2007
Minor renovation in 1999.

System	%	$	Immediate	1-5 Years	6-10 Years	11+ Years	System/Component Notes
Structure	15	$1,153,420	0	0	5	95	

Campus: Main
Bldg. No: 06
Building: Kenneth J. Smith Instructional Building
Area: 25,132sf Yr Built: 1966 Floors: 2

Use Types:
40 % Lab
60 % Classroom

Notes:
2015-Formerly called Instruction East
2007-Renovated as part of Ash Building project
2005-Building scheduled for major renovation as part of planned addition in 2006-2007
Minor renovation in 1999.

System	%	$	Immediate	1-5 Years	6-10 Years	11+ Years	System/Component Notes
Glazing	5	$384,473	0	10tne./MCID 148 >>BDC 0 Tc 6 Tw 9.548 .5 -0g08 T4 0.008Tw 5.774 -0 Td (10)8.72 518.999924411.456%5			

Campus: Main
Bldg. No: 06
Building: Kenneth J. Smith Instructional Building
Area: 23,152sf Yr Built: 1966 Floors: 2

Use Types:
40 % Lab
60 % Classroom

Notes: 2015-Formerly called Instruction East
2007-Renovated as part of Ash Building project
2005-Building scheduled for major renovation as part of planned addition in 2006-2007
Minor renovation in 1999.

System	CRV of System %	CRV of System $	Pct. of system value to budget for repair/replacement: Immediate	1-5 Years	6-10 Years	11+ Years	System/Component Notes
HVAC (continued)	25	$1,922,366	5	5	10	80	2012 assessment: System controls upgraded to DDC as part of new energy management system. Actuators on dampers and control valves replaced as required.
			$96,118	*$96,118*	*$192,237*	*$1,537,893*	

2013 - 2015 Assessment: No changes reported. No reported problems.

2016 Assessment: No changes reported. No reported problems.

2018 Assessment: The HVAC system is served by a steam to hot water heat exchanger to provide heat to perimeter classroom unit ventilators.
Chilled water is supplied by an outdoor air-cooled chiller using 25% ethylene glycol.
The current outdoor chiller is in good condition and will continue to provide 10 to 20 years.
The building controls were improved in 2009 with occupancy sensors which save energy.
It is recommended to upgrade building controls with the standard campus BEMS system.
The present classroom unit ventilators do no perform well in providing comfort & noise control
Recommend horizontal units to be replaced with improved floor mounted vertical type to provide the proper ventilation and reuse the existing distribution & control systems.

2019 Assessment: No changes reported. No reported problems.

2021 Assessment: No changes reported. No reported problems.

Campus: Main
Bldg. No: 06
Building: Kenneth J. Smith Instructional Building
Area: 23,152sf Yr Built: 1966 Floors: 2

Use Types:
40 % Lab
60 % Classroom

Notes: 2015-Formerly called Instruction East
2007-Renovated as part of Ash Building project
2005-Building scheduled for major renovation as part of planned addition in 2006-2007
Minor renovation in 1999.

System

Campus: Main
Bldg. No: 06
Building: Kenneth J. Smith Instructional Building
Area: 23,152sf Yr Built: 1966 Floors: 2

Use Types:
40 % Lab
60 % Classroom

Notes:
2015-Formerly called Instruction East
2007-Renovated as part of Ash Building project
2005-Building scheduled for major renovation as part of planned addition in 2006-2007
Minor renovation in 1999.

System	%	$	Immediate	1-5 Years	6-10 Years	11+ Years	System/Component Notes
Voice/Data	5	$384,473	0	5	10	85	Recently updated
			$0	*$19,224*	*$38,447*	*$326,802*	

2007 Assessment:No changes. No reported problems.

2009-2014 assessment:No changes reported. No reported problems.

Campus: Main
Bldg. No: 06
Building: Kenneth J. Smith Instructional Building
Area: 23,152sf Yr Built: 1966 Floors: 2

Use Types:
40 % Lab
60 % Classroom

Notes: 2015-Formerly called Instruction East
2007-Renovated as part of Ash Building project
2005-Building scheduled for major renovation as part of planned addition in 2006-2007
Minor renovation in 1999.

System	%	$	Immediate	1-5 Years	6-10 Years	11+ Years	System/Component Notes
Doors	2	$153,789	0	0	20	80	Exterior: original hollow metal doors
			$0	*$0*	*$30,758*	*$123,031*	

2005-hinges and hardware failing and deteriorating, doors rusting at bottoms, due for replacement.

Interior: Original solid core wood doors. Finish worn ,some swelling.

2007 Assessment:
Exterior: (3) exterior doors replaced

Interior: (3) new doors added, (2) removed.

2009-2012 assessment:No changes reported. No reported problems.

2013 assessment:
Classroom door hardware changed to lockdown type for security.

2014 Assessment: No changes reported.

Campus: Main
Bldg. No: 06
Building: Kenneth J. Smith Instructional Building
Area: 23,152sf Yr Built: 1966 Floors: 2

Use Types:
40 % Lab
60 % Classroom

Notes: 2015-Formerly called Instruction East
2007-Renovated as part of Ash Building project
2005-Building scheduled for major renovation as part of planned addition in 2006-2007
Minor renovation in 1999.

System	%	$	Immediate	1-5 Years	6-10 Years	11+ Years	System/Component Notes
Floors	3	$230,684	0	0	20	80	Quarry tile in corridors, no reported problems.
			$0	*$0*	*$46,137*	*$184,547*	Some new carpet, new VCT.
							2004-Some offices still need new carpet.
							2007 Assessment: flooring replaced as required by renovation. Sheet vinyl installed in labs. VCT installed in small portions of classrooms (near sinks). Carpet installed in office, some classrooms.
							2009-2014 assessment:No changes reported. No reported problems.
							2015 assessment: No changes reported. No reported problems.
							2018 Assessment: No changes reported. No reported problems. Carpet replacement in selected area.
							2019 Assessment: No changes reported. No reported problems.
							2021 Assessment: No changes reported. No reported problems.
Bldg., Fire, ADA, Elevators	2	$153,789	0	0	10	90	Stairway doors propped open on lower level.
			$0	*$0*	*$15,379*	*$138,410*	

Campus: Main
Bldg. No: 06
Building: Kenneth J. Smith Instructional Building
Area: 23,152sf Yr Built: 1966 Floors: 2

Use Types:
40 % Lab
60 % Classroom

Notes: 2015-Formerly called Instruction East
2007-Renovated as part of Ash Building project
2005-Building scheduled for major renovation as part of planned addition in 2006-2007
Minor renovation in 1999.

System	%	$	Immediate	1-5 Years	6-10 Years	11+ Years	System/Component Notes
Immed. Site, Ext. Ltg., etc	3	$230,684	0	0	10	90	No reported problems
			$0	*$0*	*$23,068*	*$207,616*	

2007 Assessment:
Sitework performed as part of Ash Building construction.
No reported problems.

2009-2014 assessment:No changes reported. No reported problems.

2015, 2018, 2019, 2021 assessment: No changes reported. No reported problems.

CRV Totals:	100	$7,689,465	*$115,342*	*$365,250*	*$811,239*	*$6,397,635*	$7,689,465

$115,342	$0	1.5%	GOOD	0-5 Year Cumulative Data

Campus: Main

Use Types:

Campus: Main
Bldg. No: 07
Building: Instruction North
Area: 21,780sf Yr Built: 1968 Floors: 1

Use Types:
100% Vo/Tech

Notes: 2007-majority of building renovated. North and south exterior walls replaced.
2005-Building scheduled for major repairs and renovation as part of Instruction East work in 2006-2007
One classroom renovated in 2001.

System	CRV of Syste %	CRV of Syste $	Pct. of system value to budget for repair/repla Immediate	1-5 Years	6-10 Years	11+ Years	System/Component Notes
Roof	7	$304,893	0	0	80	20	Trocal roof in 1998
			$0	*$0*	*$243,914*	*$60,979*	

2003-icecicles and roof runoff clinging to drip edge (covered over with Trocal roof), running down wall and into mortar joints, causing severe wall damage. Lack of gutters exacerbating problem.

2007 assessment: Gutters and downspouts added. No reported problems

2009 Assessment:No changes reported.

2010 Assessment:No changes reported.

2011 assessment: Minor roof leaks repaired as part of annual maintenance. Roof inspected annually, no reported problems, but roof nearing end of expected life.

2012 assessment:No changes reported.

2013 assessment:No changes reported.

2014 assessment: Roof inspected, due for replacement within 5 years.

2015 assessment: Roof membrane near end of expected life. Projected roof membrane replacement from roof report: 2019

2018 Assessment: Single-ply membrane with insulation.
Roof replacement scheduled in 2024.

2019 Assessment: No changes reported. No reported problems.

2021 Assessment: No changes reported. No reported problems.

Campus: Main
Bldg. No: 07

Use Types:
100% Vo/Tech

Notes: 2007-majority of building renovated. North and south exterior walls replaced.

Campus: Main
Bldg. No: 07
Building: Instruction North

Use Types:
100% Vo/Tech

Notes: 2007-majority of building renovated. North and south exterior walls replaced.
2005-Building scheduled for major repairs and renovation as part of Instruction East work in 2006-2007
One classroom renovated in 2001.

Campus: Main
Bldg. No: 07
Building: Instruction North
Area: 21,780sf Yr Built: 1968 Floors: 1

Use Types:
100% Vo/Tech

Notes: 2007-majority of building renovated. North and south exterior walls replaced.
2005-Building scheduled for major repairs and renovation as part of Instruction East work in 2006-2007
One classroom renovated in 2001.

System	%	$	Immediate	1-5 Years

2021 Assessment: No changes reported. No reported problems.

Campus: Main
Bldg. No: 07
Building: Instruction North
Area: 21,780sf Yr Built: 1968 Floors:1

Use Types:
100% Vo/Tech

Notes: 2007-majority of building renovated. North and south exterior walls replaced.
2005-Building scheduled for major repairs and renovation as part of Instruction East work in 2006-2007
One classroom renovated in 2001.

System	%	$	Immediate	1-5 Years	6-10 Years	11+ Years	System/Component Notes
Lighting	5	$217,781	5 *$10,889*	5 *$10,889*	5 *$10,889*	85 *$185,113*	Majority original T12, working, with no more than typical ballast replacement. 2007 assessment: East half of building - all lighting replaced with T8 fixtures. No "Darkroom in use" warning light installed outside darkroom door. West half of building - original lighting remains. No reported problems 2009-2011 Assessment:No changes reported. 2012 assessment:No changes reported. Lighting upgrades not required. 2013-2015 Assessment: No changes reported. No reported problems. 2016 Assessment: No changes reported. No reported problems. 2018 Assessment: Majority of lighting is T8 linear fluorescent, though some T12 lamps. T12 have been phased out due to energy efficiency, these should be replaced with LEDs. Exterior wall packs are compact fluorescent with battery packs. While previously appropriate, these are not the best solution for exterior lighting in northern climate, as it is difficult to start in cold weather with light output significantly reduced. Recommend replacement with LED wall packs. 2019, 2021 Assessment: No changes reported. No reported problems.

Campus: Main
Bldg. No: 07

Use Types:
100% Vo/Tech

Notes: 2007-majority of building renovated. North and south exterior walls replaced.

Campus: Main
Bldg. No: 07
Building: Instruction North
Area: 21,780sf Yr Built: 1968 Floors: 1

Use Types:
100% Vo/Tech

Notes: 2007-majority of building renovated. North and south exterior walls replaced.
2005-Building scheduled for major repairs and renovation as part of Instruction East work in 2006-2007
One classroom renovated in 2001.

System	%	$	Immediate	1-5 Years	6-10 Years	11+ Years	System/Component Notes
Doors	3	$130,668	5	10	10	75	Exterior hollow metal doors rusting, sills deteriorating, a few replaced in 1998.
			$6,533	*$13,067*	*$13,067*	*$98,001*	
							2002-main OH door replaced, others OK.
							Damage to lintels and jambs may require removal of doors to repair. Interior doors OK.
							2007 assessment: All exterior man and overhead doors and frames replaced. East half of building - interior doors replaced.

2019 Assessment: No changes reported. No reported problems.

2021 Assessment: No changes reported. No reported problems.

Campus: Main
Bldg. No: 07
Building: Instruction North
Area: 21,780sf Yr Built: 1968 Floors: 1

Use Types:
100% Vo/Tech

Notes: 2007-majority of building renovated. North and south exterior walls replaced.
2005-Building scheduled for major repairs and renovation as part of Instruction East work in 2006-2007
One classroom renovated in 2001.

System	%	$	Immediate	1-5 Years	6-10 Years

Campus: Main

Use Types:

Notes:

Campus: Main
Bldg. No: 08
Building: Les Morford Instructional Building
Area: 11,184sf Yr Built: 1969 Floors: 1

Use Types:
55 % Auditorium
45 % Classroom

Notes:
2015-Formerly called Instruction West
2007-covered walkway to Ash Building added.

System	CRV of System %	CRV of System $	Pct. of system value to budget for repair/replacement: Immediate	1-5 Years	6-10 Years	11+ Years	System/Component Notes
Structure	15	$507,418	0	5	10	85	No reported problems
			$0	*$25,371*	*$50,742*	*$431,305*	
							2007 assessment:No changes. No reported problems. 2009-2015 Assessment: No changes reported. No reported problems. 2016 Assessment: No changes reported. No reported problems. 2018 Assessment: Penthouse screen wall support steel has significant corrosion – will need cleaning and paint. Penthouse block cracked at support steel bearing due to thermal expansion contraction – slide bearing will be required to prevent continued deterioration Efflorescence on face of Penthouse block indicates moisture penetration into wall – block should be painted or sealed. Possible clogged roof drain on Penthouse roof. 2019, 2021 Assessment: No changes reported. No reported problems.
Roof	5	$169,139	0	5	75	20	Firestone EPDM in 1999
			$0	*$8,457*	*$126,854*	*$33,828*	
							2005 - some flashing due for replacement 2007 assessment: Flashing problems resolved during construction of covered walkway to Ash Building. 2009 Assessment:No changes reported. 2010 Assessment: Minor roof leaks discovered, repaired under warranty. 2011 assessment: Leaks Resolved. Roof inspected annually, no reported problems, but roof past half of expected life. 2012 assessment:No changes reported. 2013 assessment: Minor roof leaks at penthouse on west side. Extending membrane up to wall flashing to eliminate leaks.

							2014 assessment: Roof inspected, repaired with new RTU installation. 2015 assessment: Projected roof membrane replacement from roof report: 2024 2016 Assessment: No changes reported. No reported problems. 2018 Assessment: Roof scheduled for replacement in 2024. 2019 Assessment: No changes reported. No reported problems. 2021 Assessment: No changes reported. No reported problems. Projected roof replacement in 2026.
Glazing	5	$169,139	0	0	15	85	Original - good condition
			$0	*$0*	*$25,371*	*$143,768*	2007 assessment:No changes. No reported problems. 2009 -2015 Assessment: No changes reported. No reported problems. 2016, 2018, 2019, 2021 Assessment: No changes reported. No reported problems.
Cladding	5	$169,139	0	0	5	95	Brick, No reported problems
			$0	*$0*	*$8,457*	*$160,682*	2007 assessment:No changes. No reported problems. 2009-2016 Assessment: No changes reported. No reported problems. 2016, 2018, 2019, 2021 Assessment: No changes reported. No reported problems.

Campus: Main
Bldg. No: 08
Building: Les Morford Instructional Building
Area: 11,184sf Yr Built: 1969 Floors: 1

Use Types:
55 % Auditorium
45 % Classroom

Notes: 2015-Formerly called Instruction West
2007-covered walkway to Ash Building added.

System	%	$	Immediate	1-5 Years	6-10 Years	11+ Years	System/Component Notes
HVAC	25	$845,696	5	5	20	70	(2) AHU's in penthouse
			$42,285	*$42,285*	*$169,139*	*$591,987*	(2) rooftop condenser units for AC. Original Pneumatic controls at end of life 2003-some piping deterioration possible - continue to monitor condition 2004-major system components due for replacement ($225,000), scheduled for 2006. 2007 assessment: system components scheduled for replacement not yet done. steam line to building replaced. (2) AHU's in penthouse original, at end of life, due for replacement. (2) rooftop condenser units original, at end of life, due for replacement. Coolant leaks slowly, but units functioning. Pneumatic controls functioning. 2009 Assessment:No changes reported. 2010 Assessment: Gas meter systems replaced by Consumers Energy. HVAC system still due for upgrade / replacement. 2011 assessment:No changes reported-9.7 (er)-3 8o-9.7.5 (t)-0.9 (ed-9.7 ((t)-0.9 (ed-9.7 ((t)15.1 .7 (y)21 (

Campus: Main
Bldg. No: 08

Use Types:
55 % Auditorium

Notes: 2015-Formerly called Instruction West

Campus: Main
Bldg. No: 08
Building: Les Morford Instructional Building
Area: 11,184sf Yr Built: 1969 Floors: 1

Use Types:
55 % Auditorium
45 % Classroom

Notes:
2015-Formerly called Instruction West
2007-covered walkway to Ash Building added.

System	%	$	Immediate	1-5 Years	6-10 Years	11+ Years	System/Component Notes
Primary/Secondary	10	$338,279	0	0	10	90	No reported problems
			$0	*$0*	*$33,828*	*$304,451*	

2007 assessment:No changes. No reported problems.

2009 Assessment:No changes reported.

2010 assessment: Campus primary service upgraded by Consumers Energy to provide additional capacity.

2011-2015 Assessment: No changes reported. No reported problems.

2016 Assessment: No changes reported. No reported problems.

2018 Assessment: The main panel is a new Eaton PRL3a panel serving the building 200A at 480/277V, 3 phase. The source of this 480V is not apparent, though it is likely fed from the unit substation in the basement of the Smith Building.
The existing fire alarm system head-end is upgraded to a National Time & Signal PT series, but many of the devices are original.
The pull stations are not at a height that complies with current ADA requirements.

2019 Assessment: No changes reported. No reported problems.

Campus: Main
Bldg. No: 08
Building: Les Morford Instructional Building

Use Types:
55 % Auditorium
45 % Classroom

Notes:
2015-Formerly called Instruction West
2007-covered walkway to Ash Building added.

Campus: Main
Bldg. No: 08
Building: Les Morford Instructional Building
Area: 11,184sf Yr Built: 1969 Floors:1

Use Types:
55 % Auditorium
45 % Classroom

Notes: 2015-Formerly called Instruction West
2007-covered walkway to Ash Building added.

System	%	$	Immediate	1-5 Years	6-10 Years	11+ Years	System/Component Notes
Voice/Data	5	$169,139	0	0	5	95	Recently upgraded
			$0	[illegible]	[illegible]		

Campus: Main
Bldg. No: 08
Building: Les Morford Instructional Building
Area: 11,184sf Yr Built: 1969 Floors: 1

Use Types:
55 % Auditorium
45 % Classroom

Notes: 2015-Formerly called Instruction West
2007-covered walkway to Ash Building added.

System	%	$	Immediate	1-5 Years	6-10 Years	11+ Years	System/Component Notes
Floors	3	$101,484	5	5	15	75	Offices - carpet replaced in 2002.
			$5,074	*$5,074*	*$15,223*	*$76,113*	

2007 Assessment: No changes. No reported problems.

2009-2013 Ass60

Campus: Main
Bldg. No: 09
Building: Donald C. Burns Library and Admin.
Area: 28,720sf Yr Built: 1966 Floors: 2

Use Types:
60 % Administration
40 % Library

Notes: 2015-Formerly called LRC/Admin Building
Complete interior renovation in 1999.
2019 - New writing lab completed at library

System	%	$	Immediate	1-5 Years	6-10 Years	11+ Years	System/Component Notes
Structure	15	$1,302,399	0	0	5	95	No reported problems
			$0	*$0*	*$65,120*	*$1,237,279*	
							2007 assessment:No changes. No reported problems.

Campus: Main
Bldg. No: 09
Building: Donald C. Burns Library and Admin.
Area: 28,720sf Yr Built: 1966 Floors: 2

Use Types:
60 % Administration
40 % Library

Notes: 2015-Formerly called LRC/Admin Building
Complete interior renovation in 1999.

System	CRV of Syste %	CRV of Syste $	Pct. of system value to budget for repair/repla Immediate	1-5 Years	6-10 Years	11+ Years	System/Component Notes
Glazing	5	$434,133	0	0	20	80	Mostly original, in good condition
			$0	*$0*	*$86,827*	*$347,306*	2007 assessment:No changes. No reported problems. 2009-2011 Assessment:No changes reported. 2012 assessment: Glass replaced on 3 offices in southwestern corner. 2013-2015 Assessment: No changes reported. No reported problems. 2016, 2018, 2019, 2021 Assessment: No changes reported. No reported problems.
Cladding	6	$520,960	0	0	20	80	No reported problems
			$0	*$0*	*$104,192*	*$416,768*	2007 assessment: Brick screen wall surrounding chillers: brick at top of wall and at louvers are deteriorating - mortar loosening, some bricks loose, due for tuckpointing. 2009-2010 Assessment:No changes reported. 2011 assessment:No changes reported. Masonry at louvers still due for repair. 2012-2015 Assessment: No changes reported. Masonry at louvers still due for repair. 2016 assessment: Masonry at air louvers budgeted for repair in 2016. 2018, 2019, 2021 Assessment: No changes reported. No reported problems.

Campus: Main
Bldg. No: 09
Building: Donald C. Burns Library and Admin.
Area: 28,720sf Yr Built: 1966 Floors: 2

Use Types:
60 % Administration
40 % Library

Notes: 2015-Formerly called LRC/Admin Building
Complete interior renovation in 1999.

System	%	$	Immediate	1-5 Years	6-10 Years	11+ Years	System/Component Notes
HVAC	25	$2,170,665	0	10	20	70	Replaced in 1999, No reported problems.
			$0	*$217,067*	*$434,133*	*$1,519,466*	Variable Frequency Drive controls failing, recently replaced.
							Library humidity requirements (low humidity) handled through overcooling of space.
							2007 assessment:No changes. No reported problems.

Campus: Main
Bldg. No: 09
Building: Donald C. Burns Library and Admin.
Area: 28,720sf Yr Built: 1966 Floors: 2

Use Types:
60 % Administration
40 % Library

Notes: 2015-Formerly called LRC/Admin Building
Complete interior renovation in 1999.

System	%	$	Immediate	1-5 Years	6-10 Years	11+ Years	System/Component Notes
Plumbing/Drainage	5	$434,133	0 *$0*	10 *$43,413*	15 *$65,120*	75 *$325,600*	Some original roof drains, No reported problems 2007 assessment:No changes. No reported problem. 2009-2014 assessment:No changes reported. No reported problems. 2015 Assessment: No changes reported. No reported problems. 2016 assessment:lower level flooded during heavy rainstorm in 2016. Damage reported as minor. 2018 Assessment: The building is a 2-story fully sprinkled building. 2019, 2021 Assessment: No changes reported. No reported problems.
Primary/Secondary	9	$781,439	0 *$0*	0 *$0*	20 *$156,288*	80 *$625,152*	No reported problems

2007 assessm

Campus: Main
Bldg. No: 09
Building: Donald C. Burns Library and Admin.
Area: 28,720sf Yr Built: 1966 Floors: 2

Use Types:
60 % Administration
40 % Library

Notes: 2015-Formerly called LRC/Admin Building
Complete interior renovation in 1999.

System	%	$	Immediate	1-5 Years	6-10 Years	11+ Years	System/Component Notes
Distribution	4	$347,306	0	10	15	75	No reported problems
			$0	*$34,731*	*$52,096*	*$260,480*	

4 $347,7d pr10101575No reported problems 4

Campus: Main
Bldg. No: 09
Building: Donald C. Burns Library and Admin.
Area: 28,720sf Yr Built: 1966 Floors: 2

Use Types:
60 % Administration
40 % Library

Notes: 2015-Formerly called LRC/Admin Building
Complete interior renovation in 1999.

System	CRV of Syste %	CRV of Syste $	Pct. of system value to budget for repair/repla Immediate	1-5 Years	6-10 Years	11+ Years	System/Component Notes
Ceilings	3	$260,480	0 *$0*	5 *$13,024*	15 *$39,072*	80 *$208,384*	No reported problems 2007 assessment:No changes. No reported problems. 2009-2015 Assessment: No changes reported. No reported problems. 2016 Assessment: No changes reported. No reported problems. 2018 Assessment: There is evidence of high humidity in the lower level library where ceiling tiles are sagging. 2019, 2021 Assessment: No changes reported. No reported problems.
Walls/Casework	2	$173,653	0 *$0*	5 *$8,683*	15 *$26,048*	80 *$138,923*	No reported problems 2007 assessment:No changes. No reported problems. 2009-2015 Assessment: No changes reported. No reported problems. 2016, 2018, 2019, 2021 Assessment: No changes reported. No reported problems.
Doors	2	$173,653	0 *$0*	5 *$8,683*	15 *$26,048*	80 *$138,923*	Some doors on lower level original, working, but finish worn. 2007 assessment:No changes. No reported problems. 2009-2015 Assessment: No changes reported. 2016 Assessment: No changes reported. Lower level wood door finish due for replacement. Flood may have incerased deterioration. 2018 Assessment: No changes reported. 2019, 2021 Assessment: No changes reported. No reported problems.

Campus: Main
Bldg. No: 09

Use Types:
60 % Administration

Notes: 2015-Formerly called LRC/Admin Building
Complete interior renovation in 1999.

Campus: Main
Bldg. No: 09

Use Types:
60 % Administration

Notes: 2015-Formerly called LRC/Admin Building
Complete interior renovation in 1999.

2018 Assessment: Some retaining wall repair was completed in 2017.

2019 Assessment: No changes reported. No reported problems.

2021 Assessment: No changes reported. No reported problems.

CRV Totals:	100	$8,682,660	*$104,192*	*$442,816*	*$1,558,537*	*$6,577,115*	$8,682,660				
	Priority Issues Data					0-5 Year Cumulative Data					
		$104,192	$0	1.2%	GOOD	$547,008	$377,696	6.3%	$173,653	FAIR	
		DMB	EXCESS	FCI	RATING	DMB	EXCESS	FCI	$/YR MAINTAIN	RATING	

Campus: Main
Bldg. No: 10
Building: Pole Barn
Area: 1,800sf

Use Types:
100% Storage

Notes:

Yr Bl476.29 (or)-7.412TJ En

Walls/Casework	0	$0	0 *$0*	0 *$0*	0 *$0*	100 *$0*	N/A 2014 - 2015 Assessment: No changes reported. 2016, 2018, 2019, 2021 Assessment: No changes reported. No reported problems.
Doors	10	$17,136	0 *$0*	0 *$0*	20 *$3,427*	80 *$13,709*	4 overhead doors, 1 man door, No reported problems 2007 assessment:No changes. No reported problems. 2009-2012 assessment:No changes reported. No reported problems. 2013 Assessment: New weather seals installed at existing overhead doors. 2014 - 2015 assessment: exterior man door replaced. 2016, 2018, 2019, 2021 Assessment: No changes reported. No reported problems.
Floors	4	$6,854	0 *$0*	0 *$0*	0 *$0*	100 *$6,854*	Concrete floor 2007 assessment:No changes. No reported problems. 2009-2015 Assessment: No changes reported. No reported problems. 2016, 2018, 2019, 2021 Assessment: No changes reported. No reported problems.
Bldg., Fire, ADA, Elevators	2	$3,427	0 *$0*	0 *$0*	0 *$0*	100 *$3,427*	No reported problems 2007 assessment:No changes. No reported problems. 2009-2015 Assessment: No changes reported. No reported problems. 2016, 2018, 2019, 2021 Assessment: No changes reported. No reported problems.
Immed. Site, Ext. Ltg., etc	2	$3,427	0 *$0*	0 *$0*	0 *$0*	100 *$3,427*	No reported problems

CRV Totals:	100	$171,360	*$0*	*$12,852*	*$7,540*	*$150,968*	$171,360

Priority Issues Data					0-5 Year Cumulative Data				
CRV	$171,360	DMB	$0	EXCESS	$0	FCI	0.0%	RATING	GOOD
					$12,852	DMB	$0	FCI	7.5%
					$3,427	$/YR MAINTAIN		RATING	FAIR

Campus: Main
Bldg. No: 11
Building: Power Plant
Area: 3,840sf Yr Built: 1966 Floors: 1

Use Types:
100% Power House

Notes: 2005- Proposed renovations in 2006-2007 may require some heating system equipment and/or operation changes.
2005-Water tower due for draining/inspecting and repaint

System	%	$	Immediate	1-5 Years	6-10 Years	11+ Years	System/Component Notes
Structure	15	$371,684	0	5	5	90	Conc8ID 2668:-8.59.9 (ur) no BT -04e.7 (e10.9 (equi)-15.6 (r<</MCI0qlcbl)no B5 um(d)-12.4 (s)]TJ EMC /

Campus: Main
Bldg. No: 11
Building: Power Plant
Area: 3,840sf Yr Built: 1966 Floors: 1

Use Types:
100% Power House

Notes: 2005- Proposed renovations in 2006-2007 may require some heating system equipment and/or operation changes.
2005-Water tower due for draining/inspecting and repaint

System	%	$	Immediate	1-5 Years	6-10 Years	11+ Years	System/Component Notes
Glazing	1	$24,779	0	0	5	95	Very few windows original. OK
			$0	*$0*	*$1,239*	*$23,540*	

2007 assessment:No changes. No reported problems.

2009 Assessment: 2008-windows replaced due to forklift damage.

Ve9.61Í `

Campus: Main

Use Types:

Notes:

Campus: Main
Bldg. No: 11
Building: Power Plant
Area: 3,840sf Yr Built: 1966 Floors: 1

Use Types:
100% Power House

Notes: 2005- Proposed renovations in 2006-2007 may require some heating system equipment and/or operation changes.
2005-Water tower due for draining/inspecting and repaint

System	CRV of System %	CRV of System $	Pct. of system value to budget for repair/replacement: Immediate	1-5 Years	6-10 Years	11+ Years	System/Component Notes
Plumbing/Drainage	8	$198,232	0 *$0*	0 *$0*	20 *$39,646*	80 *$158,585*	2004 new electrical service to power plant lift station installed (two lift stations for campus), improved reliability. 2007-2014 Assessment: No changes reported. 2015 Assessment: New frequency drive added to well pump to improve water pressure. No reported problems 2016, 2018, 2019, 2021 Assessment: No changes reported. No reported problems.
Primary/Secondary	10	$247,790	0 *$0*	5 *$12,389*	15 *$37,168*	80 *$198,232*	OK. Some original 2007 assessment:No changes. No reported problems. 2009 Assessment:No changes reported. 2010 assessment: Campus primary service conductors upgraded to 8360V by Consumers Energy to provide additional capacity. 2011-2015 Assessment: No changes reported. No reported problems. 2016, 2018, 2019, 2021 Assessment: No changes reported. No reported problems.

Campus: Main
Bldg. No: 12
Building: Ash Building
Area: 28,800sf Yr Built: 2007 Floors: 2

Use Types:
40 % Lab
25 % Classroom
25 % Admin
10 % Audit

Notes: Connected to Instruction East

System	%	$	Immediate	1-5 Years	6-10 Years	11+ Years	System/Component Notes
Glazing	5	$437,110	0	0	0	100	Aluminum frame storefront system typical. Minimal curtain wall.
			$0	*$0*	*$0*	*$437,110*	
							2007-New construction, under warranty
							2009-2021 Assessment: No changes reported. No reported problems
Cladding	6	$524,532	0	0	0	100	Brick on block backup metal siding on block backup
			$0	*$0*	*$0*	*$524,532*	

Clx44 403.08 388.2 R7.4MC C 6-11.8 (d6-11.8 (on,)-4-)29cH.36 .44VACClx44 403.08 388CID 188 >>BDC 0.008 Tw -48E

2018 Assessment: The HVAC system is a combination of central AHU/ERU and appear relatively new and in good condtion.
Chilled water is supplied by an outdoor air-cooled chiller using 25% ethylene glycol.
The current outdoor chiller is in good condition and will continue to provide 10 to 20 years.
The building is fully DDC controlled with the standard campus BEMS system.
Steam and condensate services both enter in to the building and converted to hot water heating.
The present classroom unit ventilators do no perform well in providing comfort & noise control.
Recommend horizontal units to be replaced with improved floor mounted vertical type to provide the proper ventilation and reused the existing air distribution & control systems.

2019 Assessment: No changes reported. No reported problems

2021 Assessment: No changes reported. No reported problems.

Campus: Main

Use Types:

Notes:

Campus: Main
Bldg. No: 12
Building: Ash Building
Area: 28,800sf Yr Built: 2007 Floors: 2

Use Types:
40 % Lab
25 % Classroom
25 % Admin
10 % Audit

Notes: Connected to Instruction East

System	%	$	Immediate	1-5 Years	6-10 Years	11+ Years	System/Component Notes
Distribution	5	$437,110	0	0	0	100	2007-New construction, under warranty
			$0	*$0*	*$0*	*$437,110*	
							2009-2021 Assessment: No changes reported. No reported problems
Lighting	5	$437,110	0	10	5	85	All fluorescent. Linear direct/indirect pendant fixtures in classrooms and labs.
			$0	*$43,711*	*$21,855*	*$371,543*	Recessed 1x4 typical in corridors, minimal recessed cans and specialty fixtures.
							Recessed 2x4 in offices.
							2007-New construction, under warranty
							2009-2015 Assessment: No changes reported. No reported problems
							2016 Assessment: No changes reported. No reported problems
							2018 Assessment: Exterior canopy lighting regularly fills with insects.
							Recommend replacement with new, sealed LED modules.
							Exterior wall packs are compact fluorescent with battery packs.
							While previously appropriate, these are not the best solution for exterior lighting in

System	%	$	Immediate	1-5 Years	6-10 Years	11+ Years	System/Component Notes
CRV Totals:	100	$8,742,195	*$0*	*$240,410*	*$367,172*	*$8,134,612*	$8,742,195

Campus: Main
Bldg. No: 13
Building: Maintenance Building
Area: 8,000sf Yr Built: 2007 Floors: 1

Use Types:
100% Storage

Notes: Pole barn building with 3 offices.
2016-Replacement value corrected to match construction type.

System	%	$	Immediate	1-5 Years	6-10 Years	11+ Years

Campus: Main
Bldg. No: 13
Building: Maintenance Building
Area: 8,000sf Yr Built: 2007 Floors: 1

Use Types:
100% Storage

Notes: Pole barn building with 3 offices.
2016-Replacement value corrected to match consruction type.

System	CRV of Syste %	CRV of Syste $	Pct. of system value to budget for repair/repla Immediate	1-5 Years	6-10 Years	11+ Years	System/Component Notes
Glazing	2	$9,030	0	0	0	100	Minimal windows - (7) vinyl clad sliders in office areas.
			$0	*$0*	*$0*	*$9,030*	
							2007-New construction, under warranty
							2009-2021 Assessment: No changes reported. No reported problems
Cladding	15	$67,725	0	0	0	100	prepainted metal siding with blown-in cellulose insulation
			$0	*$0*	*$0*	*$67,725*	
							2007-New construction, under warranty
							2009-2021 Assessment: No changes reported. No reported problems
HVAC	15	$67,725	0	0	0	100	(3) stand alone electric in-wall heaters/AC units in offices.
			$0	*$0*	*$0*	*$67,725*	Gas-fired radiant heaters in shop area.
							2007-New construction, under warranty
							2009 Assessment:No changes reported.
							2010 Assessment: Gas meter systems replaced by Consumers Energy.
							2011 assessment:No changes reported. No reported problems.
							2012 assessment: Energy Management System upgraded as part of ECM contract.
							2013-2018 Assessment: No changes reported. No reported problems
							2019 Assessment: Replace two heaters. No reported problems.
							2021 Assessment: No changes reported. No reported problems.
Plumbing/Drainage	5	$22,575	0	0	0	100	Minimal plumbing - 1 toilet room, work sink, hose bibbs.
			$0	*$0*	*$0*	*$22,575*	Linear floor drain with oil separator in shop area.
							2007-New construction, under warranty
							2009-2021 Assessment: No changes reported. No reported problems

Campus: Main
Bldg. No: 13
Building: Maintenance Building
Area: 8,000sf Yr Built: 2007 Floors: 1

Use Types:
100% Storage

Notes: Pole barn building with 3 offices.
2016-Replacement value corrected to match consruction type.

System	%	$

Campus: Main
Bldg. No: 13
Building: Maintenance Building
Area: 8,000sf Yr Built: 2007 Floors: 1

Use Types:
100% Storage

Notes: Pole barn building with 3 offices.
2016-Replacement value corrected to match consruction type.

System	CRV of Syste %	CRV of Syste $	Pct. of system value to budget for repair/repla Immediate	1-5 Years	6-10 Years	11+ Years	System/Component Notes
Walls/Casework	5	$22,575	0	0	0	100	Painted gypsum board walls between offices and shop areas.
			$0	*$0*	*$0*	*$22,575*	
							2007-New construction, under warranty
							2009-2021 Assessment: No changes reported. No reported problems
Doors	4	$18,060	0	0	0	100	(1) overhead door in shop area.
			$0	*$0*	*$0*	*$18,060*	(1) Hollow metal exterior door.
							Hollow metal interior doors with lites.
							2007-New construction, under warranty
							2009-2021 Assessment: No changes reported. No reported problems
Floors	4	$18,060	0	0	0	100	Concrete floor in shop area.
			$0	*$0*	*$0*	*$18,060*	Carpet in offices.
							2007-New construction, under warranty
							2009-2021 Assessment: No changes reported. No reported problems

Campus: Main
Bldg. No: 13
Building: Maintenance Building
Area: 8,000sf Yr Built: 2007 Floors: 1

Use Types:
100% Storage

Notes: Pole barn building with 3 offices.
2016-Replacement value corrected to match consruction type.

System	CRV of Syste %	CRV of Syste $	Pct. of system value to budget for repair/repla Immediate	1-5 Years	6-10 Years	11+ Years	System/Component Notes
Bldg., Fire, ADA, Elevators	2	$9,030	0	0	0	100	No fire alarm system.
			$0	*$0*	*$0*	*$9,030*	No sprinkler system.
							2007-New construction, under warranty
							2009-2021 Assessment: No changes reported. No reported problems
Immed. Site, Ext. Ltg., etc	3	$13,545	0	0	0	100	Exterior lighting: wall packs
			$0	*$0*	*$0*	*$13,545*	Exterior paving: asphalt drive and parking.
							2007-New construction, under warranty
							2009-2021 Assessment: No changes reported. No reported problems
CRV Totals:	100	$451,500	*$0*	*$0*	*$36,120*	*$415,380*	

Priority Issues Data					0-5 Year Cumulative Data				
CRV	DMB	EXCESS	FCI	RATING	DMB	EXCESS	FCI	$/YR MAINTAIN	RATING
$451,500	$0	$0	0.0%	GOOD	$0	$0	0.0%	$9,030	GOOD

Campus: Greenville
Bldg. No: 14
Building: Ash Technology and Learning Center
Area: 19,495sf Yr Built: 2001 Floors: 1

Use Types:
10 % Auditorium
50 % Technology Lab
30 % Classroom
10 % Admin

Notes:

System	%	CRV of Syster $	Immediate	1-5 Years	6-10 Years	11+ Years	System/Component Notes
Structure	16	$970,922	0	2	5	93	Some CMU walls showing cracking - 2003
			$0	*$19,418*	*$48,546*	*$902,958*	
							2007 assessment: Cracking continuing at door frames - especially in center corridor.
							2009-2015 Assessment: No changes reported. No reported problems
							2016 assessment: minor grout cracking from settlement continues
							2018 Assessment: Building in good structural condition, no deficiencies noted.
							2019 Assessment: Building in good structural condition, no deficiencies noted.
							2021 Assessment: No changes reported. No reported problems.
Roof	5	$303,413	0	10	60	30	Fully adhered EPDM roof.
			$0	*$30,341*	*$182,048*	*$91,024*	
							2007 assessment:No changes. No reported problems.
							2010 Assessment:No changes reported.
							2011 assessment:No changes reported.
							2012 assessment:No changes reported.
							2013 assessment: Minor leaks at equipment curbs - repaired.
							2014 assessment: Roof inspected, multiple flashing, membrane tears and punctures repaired as necessary. Projected roof membrane replacement, per roof report: 2022
							2016 Assessment: No changes reported. No reported problems
							2018 Assessment: No changes reported. No reported problems.
							2019 Assessment: No changes reported. No reported problems.
							2021 Asdsessment: No changes reported. No reported problems.

Campus: Greenville
Bldg. No: 14

Use Types:
10 % Auditorium

Notes:

2019, 2021 Assessment: No changes reported. No reported problems.

Campus: Greenville
Bldg. No: 14
Building: Ash Technology and Learning Center
Area: 19,495sf Yr Built: 2001 Floors: 1

Use Types:
10 % Auditorium
50 % Technology Lab
30 % Classroom
10 % Admin

Notes:

System	CRV of Syste %	CRV of Syste $	Pct. of system value to budget for repair/repla Immediate	1-5 Years	6-10 Years	11+ Years	System/Component Notes
Lighting	5	$303,413	0 *$0*	10 *$30,341*	10 *$30,341*	80 *$242,731*	2007 assessment: Ballasts prone to excessive failure replaced, problem resolved. 2009-2016 Assessment: No changes reported. No reported problems 2018 Assessment: Lighting throughout the building is primarily T8 fluorescent, with classrooms containing direct/indirect fixtures on a multi-level switching scheme. Some exit signs were noted as no longer being illuminated. These are likely past their life and should be fixed or replaced. 2019, 2021 Assessment: No changes reported. No reported problems.
Voice/Data	5	$303,413	0 *$0*	0 *$0*	0 *$0*	100 *$303,413*	2007 assessment: No reported problems. 2009-2021 Assessment: No changes reported. No reported problems
Ceilings	3	$182,048	0 *$0*	0 *$0*	0 *$0*	100 *$182,048*	Some stained ceiling tiles in corridor outside M112, likely roof related, but no known recent leaks. 2007 assessment: Damaged ceiling tiles replaced. No reported problems. 2009-2021 Assessment: No changes reported. No reported problems
Walls/Casework	4	$242,731	0 *$0*	0 *$0*	5 *$12,137*	95 *$230,594*	2005-water damage to cabinets in catering kitchen from dishwasher leak 2007 - 2011 assessment:No changes. 2012 assessment: Minor renovations performed to relocate interior partitions to modify classroom sizes. 2013-2021 assessment:No changes reported. No reported problems.
Doors	2	$121,365	0 *$0*	0 *$0*	0 *$0*	100 *$121,365*	2007 assessment: No reported problems. 2009-2012 assessment:No changes reported. No reported problems. 2013 assessment: All classroom door hardware be changed to lockdown type for security.

2014-2021 Assessment: No changes reported. No reported problems

Campus: Greenville
Bldg. No: 15
Building: Braman Center
Area: 16,585sf Yr Built: 2012 Floors: 1

Use Types:
50 % Technology Lab
50 % Classroom

Notes: New construction, completed in 2013
2019 - Welding lab renovation and robotics lab renovation completed.

System	%	$	Immediate	1-5 Years	6-10 Years	11+ Years	System/Component Notes
Structure	18	$947,249	0	0	0	100	Steel frame structure, concrete slab-on-grade.
			$0	*$0*	*$0*	*$947,249*	
							2013 assessment - building complete, under warranty.
							2014 - 2015 Assessment: No changes reported. No reported problems
							2016 Assessment: No changes reported. No reported problems.
							2018 Assessment: Building in good structural condition, no deficiencies noted.
							2019, 2021 Assessment: No changes reported. No reported problems.
Roof	6	$315,750	0	0	0	100	White EPDM roof membrane.
			$0	*$0*	*$0*	*$315,750*	
							2013 assessment - building complete, under warranty.
							2014 - 2015 Assessment: No changes reported. No reported problems
							2016 Assessment: No changes reported. No reported problems. Projected roof membrane replacement from roof report: 2024
							2018, 2019, 2021 Assessment: No changes reported. No reported problems.
Glazing	3	$157,875	0	0	0	100	Aluminum framed fixed windows and clerestory. Some construction issues00

2019 Assessment: Modified glazing at new welding lab No reported problems

2021 Assessment: No changes reported. No reported problems.

Campus: Greenville
Bldg. No: 15
Building: Braman Center
Area: 16,585sf Yr Built: 2012 Floors: 1

Use Types:
50 % Technology Lab
50 % Classroom

Notes: New construction, completed in 2013

System	%	$	Immediate	1-5 Years	6-10 Years	11+ Years	System/Component Notes
Cladding	15	$789,374	0	0	0	100	Brick with metal panels at areas with windows.
			$0	*$0*	*$0*	*$789,374*	2013 assessment - building complete, under warranty.
							2014 - 2015 Assessment: No changes reported. No reported problems
							2016 - 2021 Assessment: No changes reported. No reported problems.
HVAC	15	$789,374	10	10	10	70	2 condensing boilers, ground mounted DX chillers, 1 air handler for entire building.
			$78,937	*$78,937*	*$78,937*	*$552,562*	System on DDC controls and college-9 (al)4.6 (pan83C 0.001 u ED)-3 (C)-3.1 (c)-9..9 (2 (on D)EMC /P

Campus: Greenville
Bldg. No: 15
Building: Braman Center
Area: 16,585sf Yr Built: 2012 Floors: 1

Use Types:
50 % Technology Lab
50 % Classroom

Notes: New construction, completed in 2013

Sy0D 34 >>BDC er

Campus: Greenville
Bldg. No: 15
Building: Braman Center
Area: 16,585sf Yr Built: 2012 Floors: 1

Use Types:
50 % Technology Lab
50 % Classroom

Notes: New construction, completed in 2013

System	CRV of Syste %	CRV of Syste $	Pct. of system value to budget for repair/repla Immediate	1-5 Years	6-10 Years	11+ Years	System/Component Notes
Voice/Data	3	$157,875	0	0	0	100	2013 assessment - building complete, under warranty.
			$0	*$0*	*$0*	*$157,875*	2014 - 2021 Assessment: No changes reported. No reported problems
Ceilings	4	$210,500	0	0	0	100	Combination of lay-in and open to deck in corridors & some labs, gypsum in toilet rooms.
			$0	*$0*	*$0*	*$210,500*	2013 assessment - building complete, under warranty.
							2014 - 2015 Assessment: No changes reported. No reported problems
							2018 Assessment:
							2019 Assessment: Ceiling removed in robotics lab.
							2021 Assessment: No changes reported. No reported problems.
Walls/Casework	5	$263,125	0	0	0	100	Painted drywall typical, with tile wainscots. Tile in toilet rooms.
			$0	*$0*	*$0*	*$263,125*	2013 assessment - building complete, under warranty.
							2014 - 2021 Assessment: No changes reported. No reported problems
Doors	4	$210,500	0	0	0	100	Exterior doors - aluminum full-lite doors at entries, painted hollow metal at service entries.
			$0	*$0*	*$0*	*$210,500*	Interior doors - hollow metal.
							2013 assessment - building complete, under warranty.
							2014 - 2021 Assessment: No changes reported. No reported problems

Campus: Greenville

Campus: Greenville
Bldg. No: 15
Building: Braman Center
Area: 16,585sf Yr Built: 2012 Floors: 1

Use Types:
50 % Technology Lab
50 % Classroom

Notes: New construction, completed in 2013

System	CRV of Syste %	CRV of Syste $	Pct. of system value to budget for repair/repla Immediate	1-5 Years	6-10 Years	11+ Years	System/Component Notes
CRV Totals:	100	$5,262,495	*$78,937*	*$78,937*	*$121,037*	*$4,983,583*	$5,262,495

Priority Issues Data					0-5 Year Cumulative Data				
CR	DMB	EXCESS	FCI	RATING	DMB	EXCESS	FCI	$/YR MAINTAIN	RATING
$5,262,495	$78,937	$0	1.5%	GOOD	$157,875	$0	3.0%	$105,250	GOOD

Campus: Greenville
Bldg. No: 16
Building: Greenville Pole Barn
Area: 4,900sf Yr Built: 1970 Floors: 1

Use Types:
100% Storage

Notes: Original construction date unknown. Built as part of old fairgrounds, now owned by MCC.

System	%	$	Immediate	1-5 Years	6-10 Years	11+ Years	System/Component Notes
Structure	30	$66,843	0	0	0	100	Wood pole barn structure
			$0	*$0*	*$0*	*$66,843*	
							2013 assessment - no reported problems.
							2014 Assessment: No changes reported.
							2015 - 2021 Assessment: No changes reported. No reported problems
Roof	20	$44,562	0	0	5	95	Standing seam metal roof.
			$0	*$0*	*$2,228*	*$42,334*	
							20[illegible]sment - no reported problems.
							20[illegible]ment: Roof inspected, repaired as necessarysm - 2021 Assessment: No changes reported. No
							20[illegible]
							2014 as$66,00533495es$2,$2,228

CRV Totals:	100	$222,810	*$0*	*$0*	*$4,902*	*$217,908*	$222,810					
Priority Issues Data						0-5 Year Cumulative Data						
$222,810		$0	$0	0.0%	GOOD	$0	$0	0.0%	$4,456	GOOD		
CR		DMB	EXCESS	FCI	RATING	DMB	EXCESS	FCI	$/YR MAINTAIN	RATING		